


United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Salt Lake Field Office
2370 South Decker Lake Blvd.
West Valley City, UT 84119
ph: (801) 977-4300; Fax: (801) 977-4397
www.ut.blm.gov/saltlake_fo



In Reply Refer To:
3809 (UTW011)
UTU-90510

OCT 02 2014

RECEIVED
OCT 03 2014
DIV. OF OIL, GAS & MINING

Jon Rush
Gold Rush Metals LLC
P.O. Box 212
Orderville, Utah 84758

Re: Request to repair the damage from runoff and erosion to the existing road from the Gold Hill Road to the proposed mine site, located in T. 7 S., R. 18 W., Sections 23, 26 and 35.

Dear Mr. Rush:

On August 22, 2014, our office received your request to conduct repairs to the road leading in to your proposed mining Plan of Operation (POO) located on Dutch Mountain, in Tooele County, Utah. After speaking with my staff and reviewing your request, I have determined to authorize the necessary repairs to the road under the following conditions.

- Repair only the areas that have been damaged due to erosion from the recent runoff to make the road operable for the short term until your POO is approved.
- Do not widen the existing road, all repairs must be confined to the current road width. No new road construction is authorized at this time, only repairs to the existing surface disturbance.
- All vehicles and equipment must remain on the existing road to the greatest extent possible. Avoid driving/turning vehicles and equipment overland to avoid any new disturbances that are not authorized at this time.
- Make sure that you have any other State, Local or Federal authorizations/approvals prior to conducting any surface disturbing activities associated with this authorization.

If you have any questions, please contact Larry Garahana at (801) 977-4371.

Sincerely,

Rebecca Hotze
Field Manager

cc: Leslie Heppler, UDOGM, 1594 W. North Temple, Ste. #1210, Box 145801, SLC, UT 84114-5801